

ALABAMA UNIFORM TRAFFIC ACCIDENT REPORT

Accident No.

COPIED

Shaded Areas To Be Used By Data Processing Only

Sheet 1 of 4 Sheet(s)

Microfilm No.

Local Case No.

LOCATION AND TIME		Date		Time		Day of Week		County		City		Rural		Highway Classification		Municipal		Local Zone			
09 02 2004		3:25		PM		MT		46				X		1- Interstate 2- State 3- Federal		Municipal		Local Zone			
On Street Road or Highway		At Intersection of or Between (Node 1)		And (Node 2)										01 - Occurred 02 - Prior Collision 03 - Immediate 04 - Not Immediate		NON COLLISION EVENT 05 - Pedestrian 06 - Roadside Collapse 07 - Jockeyed		08 - Police/Civilian Fall From 09 - Traffic Signal/Gate 10 - Other			
I-85		MACON COUNTY ROAD 30		MACON COUNTY ROAD 93																	
I085		7245		7205																	
Intersection Related 1 Node 1 2 Node 2 3 Not Related		Mile Post 24.50		Control Access 1 Main Rd 2 Frontage Rd		3 Interchange 4 Entrance Ramp		5 Exit Ramp 6 N/A		Prime Contr. Ctrms 27		Prime Contr. Unit No 1									
First Hazardous Event 77		Event Location 3		Distance to Fixed Object 17 FT		No. of Vehicles 1		No. Pedestrians 0		No. Bicycles 0		No. Motorcycles 0		Unit 1 Type 1		Unit 2 Type 1					
Driver Full Name VERNELL B MORRIS		Street Address 16633 STEPHANIE STREET		City and State BATON ROUGE LA		Zip 70819		Telephone No. 225 275-110													
DOB 12 03 1960		Race B		Sex M		DL State LA		Driver License No. 004380900		DL Class A		DL Status C		List Restrictions Not Completed With		CDL Status C		List Endorsements Not Completed With		Residence Less Than 25 Miles Yes (No)	
Place of Employment PANTHER II TRANSPORTATION INC. MEDINA OHIO		Liability Insurance Co. ZURICH AMERICAN INSURANCE		Social Security No. 4 3 4 1 - 1 7 1 - 5 7 1 3																	
Driver Conditions 1 - No Defect 2 - Apparently Defect 3 - Defect		Subsidiary 1 - Unknown 2 - Unknown		Officer's Opinion 1 - Yes 2 - No		Alcohol 1 - Yes 2 - No		Type Test 1 - No Test 2 - No Test		Blood Test 1 - No Test 2 - No Test		Other Contr. Circumstances 99		Prime Hazard Event 20		Event Loc 1					
Maneuver 01		Travel Road Name I-85		Road Code I085		Travel Direction N E S W A - Not on Rd		U - Unknown													
Year 1998		Make KW		Model N/A		Body NA		VIN 1XKADU9X2WJ784009		License Tag Number PVA 9210		State OH		Year 2000							
Owner's Name LAFAYETTE INVESTMENTS INC		Street or R.F.D. 104 WEST 40 HIGHWAY		City BATES CITY		State MO		Zip 64011													
Type 1 - Auto 2 - Station Wagon 3 - Pick Up 4 - Van 5 - Truck 6 - Other Truck 7 - Comm Bus 8 - School Bus 9 - Other Bus 10 - Motorcycle		Usage 1 - Personal 2 - Driver Trng. 3 - Construction 4 - Ambulance/Paramedical 5 - Military 6 - Transport Prop 7 - Agriculture 8 - Wrecker/Tow		10 - Police 11 - Other 12 - Business 13 - Bus/Pass. 14 - Fire Fighting 15 - Other		Hazardous Cargo 1 - None 2 - Explosive 3 - Gas 4 - Flammable/Combust. Liq. 5 - Flammable Solids 6 - Oxidizer/Peroxide 7 - Poison 8 - Radioactive Material 9 - Corrosive Material 10 - Other		Attachment 1 - None 2 - Mobile Home 3 - Semi Trailer 4 - Utility Trailer 5 - Wheel Trailer 6 - Boat Trailer		Contributing Defect 1 - None 2 - Brakes 3 - Steering 4 - Suspension 5 - Tires 6 - Exhaust 7 - Lights 8 - Turn Signal		Circle areas Damaged On Diagram 1 - Under Carriage 2 - Windshield 3 - Restraint Sys. 4 - Wheels 5 - Truck Coupling 6 - Cargo 7 - Fuel System 8 - Other 9 - Unknown		Enter Point of Initial Impact 10							
Speed Limit 70 MPH		Est. Speed 70 MPH		Citation Offense Charged NONE		Damage Severity 1 - Non Visible 2 - Not Disabled		Vehicle Towed Away? Yes (No)		Occupants in Unit 2		Total Injuries in Unit 2									
Vehicle Towed By Whom THROWER'S WRECKER LOT		To Where THROWER'S WRECKER LOT TUSKEGEE AL																			
Driver Full Name EDWARD NEAL THOMPSON		Street Address 801 5TH AVENUE		City and State GENEVA AL		Zip 36340		Telephone No. 334 684-394													
DOB 10 30 1962		Race W		Sex M		DL State AL		Driver License No. 4657210		DL Class AMV		DL Status C		List Restrictions Not Completed With		CDL Status C		List Endorsements Not Completed With		Residence Less Than 25 Miles Yes (No)	
Place of Employment FLORIDA TRANSFORMER		Liability Insurance Co. AIG		Social Security No. 4 1 1 7 1 - 8 1 8 1 - 9 3 1 1																	
Driver Conditions 1 - No Defect 2 - Apparently Defect 3 - Defect		Subsidiary 1 - Unknown 2 - Unknown		Officer's Opinion 1 - Yes 2 - No		Alcohol 1 - Yes 2 - No		Type Test 1 - No Test 2 - No Test		Blood Test 1 - No Test 2 - No Test		Other Contr. Circumstances 97		Prime Hazard Event 20		Event Loc 1					
Maneuver 01		Travel Road Name I-85		Road Code I085		Travel Direction N E S W A - Not on Rd		U - Unknown													
Year 1995		Make PTRB		Model N/A		Body NA		VIN 1XP5DB9X0SN376286		License Tag Number A50 6TP		State FL		Year 2000							
Owner's Name FLORIDA TRANSFORMER		Street or R.F.D. PO BOX 507		City DEFUNIAK SPRINGS		State FL		Zip 32435													
Type 1 - Auto 2 - Station Wagon 3 - Pick Up 4 - Van 5 - Truck 6 - Other Truck 7 - Comm Bus 8 - School Bus 9 - Other Bus 10 - Motorcycle		Usage 1 - Personal 2 - Driver Trng. 3 - Construction 4 - Ambulance/Paramedical 5 - Military 6 - Transport Prop 7 - Agriculture 8 - Wrecker/Tow		10 - Police 11 - Other 12 - Business 13 - Bus/Pass. 14 - Fire Fighting 15 - Other		Hazardous Cargo 1 - None 2 - Explosive 3 - Gas 4 - Flammable/Combust. Liq. 5 - Flammable Solids 6 - Oxidizer/Peroxide 7 - Poison 8 - Radioactive Material 9 - Corrosive Material 10 - Other		Attachment 1 - None 2 - Mobile Home 3 - Semi Trailer 4 - Utility Trailer 5 - Wheel Trailer 6 - Boat Trailer		Contributing Defect 1 - None 2 - Brakes 3 - Steering 4 - Suspension 5 - Tires 6 - Exhaust 7 - Lights 8 - Turn Signal		Circle areas Damaged On Diagram 1 - Under Carriage 2 - Windshield 3 - Restraint Sys. 4 - Wheels 5 - Truck Coupling 6 - Cargo 7 - Fuel System 8 - Other 9 - Unknown		Enter Point of Initial Impact 1							
Speed Limit 70 MPH		Est. Speed 70 MPH		Citation Offense Charged NONE		Damage Severity 1 - Non Visible 2 - Not Disabled		Vehicle Towed Away? Yes (No)		Occupants in Unit 2		Total Injuries in Unit 2									
Vehicle Towed By Whom THROWER'S WRECKER SERVICE		To Where THROWER'S WRECKER LOT TUSKEGEE AL																			
Contributing Circumstances 01 - Improper Passing 02 - Improper Lane Change/Overlap 03 - Improper Turn/Shift 04 - Following Too Close 05 - Misperceived Stopping Dist. 06 - Over Speed Limit 07 - Avoidance/Reaction/Vis. 08 - Unseen Object/Person/Vis. 09 - Improper Backing 10 - Loss Traffic Control 11 - Improper Signal 12 - Failure to Yield Right of Way		Driver's Action 01 - On Straight Ahead 02 - Pass on Left 03 - Pass on Right 04 - Pass on Right 05 - On Straight Ahead 06 - Change Lane - Left 07 - Change Lane - Right 08 - Merge - Left 09 - Merge - Right 10 - Wrong Side of Road 11 - Wrong Way - 1 Way		Driver's Action 13 - Right Turn 14 - Left Turn 15 - U-Turn 16 - Start From Park 17 - Start in Traffic 18 - Stopped in Traffic 19 - Avoid Obstacle in Road 20 - Exiting Private Road/Property 21 - Pedestrian Ride with Traffic in Road 22 - Pedestrian Ride with Traffic on Road 23 - Pedestrian Ride Against Traffic in Rd		Pedestrian Action 01 - Cross/Enter Intersection 02 - Walk in Road - With Traffic 03 - Walk in Road - Against Traffic 04 - Stand in Roadway 05 - Get out of Vehicle 06 - Push/Pull on Vehicle 07 - Push/Pull on Vehicle 08 - Push/Pull on Vehicle 09 - Push/Pull on Vehicle 10 - Push/Pull on Vehicle 11 - Not in Road 12 - Unknown		Event Location 1 - On Roadway 2 - Off Roadway 3 - Unknown 4 - Driveway 5 - Private Road/Property 6 - Intersection													

EXHIBIT D

SEATING		Other Involved Unit (Circle One)		Other Involved Unit (Circle One)		Other Involved Unit (Circle One)		CODES	
Unit 1	Unit 2	Unit 1	Unit 2	Unit 1	Unit 2	Unit 1	Unit 2	SAFETY EQUIPMENT	
12 - Pedestrian 13 - Rider of Domestic Animal 14 - Occ. of Non-Motorized Vehicle 15 - Victim of Other Circumstance/ Codes Not Applicable		12 - Pedestrian 13 - Rider of Domestic Animal 14 - Occ. of Non-Motorized Vehicle 15 - Victim of Other Circumstance/ Codes Not Applicable		12 - Pedestrian 13 - Rider of Domestic Animal 14 - Occ. of Non-Motorized Vehicle 15 - Victim of Other Circumstance/ Codes Not Applicable		12 - Pedestrian 13 - Rider of Domestic Animal 14 - Occ. of Non-Motorized Vehicle 15 - Victim of Other Circumstance/ Codes Not Applicable		01 - None Installed 02 - Not Applicable 03 - Unknown (Any Type) 04 - Lap Belt Only 05 - Fastened 06 - Not Fastened 07 - Lap/Shoulder Harness 08 - Lap Only Used 09 - Neither Used 10 - Shoulder Only Used 11 - Both Used 12 - Motorcycle Helmet 13 - None Used 14 - Used 15 - Air Bag 16 - Deployed, Belts Used 17 - Not Deployed, Belts Used 18 - Deployed, Belts Not Used 19 - Not Deployed, Belts Not Used 20 - Child Restraint 21 - Child Restraint Used 22 - Other Restraint Used 23 - None Used 24 - Pedal Cycle/Pedestrian 25 - Contrasting Clothing 26 - Non-contrasting Clothing	
VICTIMS		Name		Address		Unit No		Seat Pos	
N/A		VERNELL B MORRIS		16633 STEPHANIE ST BATON ROUGE LA		1		1	
N/A		ALABAMA DEPT OF FORENSIC SCIENCES MONTGOMERY AL		ALDFS		Taken By			
N/A		EDWARD NEAL THOMPSON		801 5TH AVENUE GENEVA AL		2		1	
N/A		TALLASSEE COMMUNITY HOSPITAL TALLASSEE AL		CARE AMBULANCE		Taken By			
CODES		Injury Type		Ejected		First Aid By		First Aid By	
K Killed B Bruise/Abrasion/Swelling		A - Visible or Carried from Scene C - Not Visible—Has Pain/Faint		N - Not F - Fully P - Partially		T - Trapped U - Unknown A - Not Applicable		A - Ambulance Attended D - Doctor M - Paramedic O - Other P - Police U - Unknown N - None	
NARRATIVE AND DIAGRAM									
Officer's Opinion of What Happened: SEE SUPPLEMENTAL SHEET									
ROADWAY ENVIRONMENT									
For Each Roadway Environment Field, Circle One Entry for Each Involved Unit Unit 1: 1 - None, 2 - Shoulders Low, 3 - Shoulders High, 4 - Holes, Bumps, Etc., 5 - Other Unit 2: 1 - None, 2 - Shoulders Low, 3 - Shoulders High, 4 - Holes, Bumps, Etc., 5 - Other Surface Construction: 1 - Asphalt, 2 - Concrete, 3 - Brick, 4 - Unpaved, 5 - Other Condition: 1 - Dry, 2 - Wet, 3 - Ice, 4 - Snowy/Slushy, 5 - Muddy, 6 - Other Accident In Or Related To Road Construction Zone? Yes/No Material In Roadway (Contributing): 1 - None, 2 - Rocks, 3 - Trees/Limbs, 4 - Dirt, 5 - Gravel, 6 - Oil/Petrol, 7 - Other Material Source: 1 - Not Applicable, 2 - Natural Environment, 3 - Dropped From Vehicle, 4 - Already In Road, But Fell From Vehicle, 5 - Other, 6 - Unknown Character: 1 - Straight—Level, 2 - Straight—Down Grade, 3 - Straight—Up Grade, 4 - Straight—Hillcrest, 5 - Curve—Level, 6 - Curve—Down Grade, 7 - Curve—Up Grade, 8 - Curve—Hillcrest									
Vision Obscured By: 1 - Buildings, 2 - Signboards, 3 - Trees, Crops, Bushes, 4 - Blowing Snow/Sand, 5 - Hillcrest, 6 - Curve in Road, 7 - Fog, 8 - Parked Vehicle, 9 - Moving Vehicle(s), 10 - Blinded by Sunlight, 11 - Fire/Smoke, 12 - Dust, 13 - Blinded by Headlights, 14 - Embankment, 15 - Rain on Windshield, 16 - Snow on Windshield, 17 - Other, 18 - Unknown Traffic Control: 1 - Police Officer, 2 - R.R. Crossing Gates, 3 - R.R. Flashing Lights, 4 - R.R. Cross Buck/Pave Mark, 5 - Pedestrian Control, 6 - Traffic Signal, 7 - Flashing Beacon, 8 - Stop Sign, 9 - Yield Sign, 10 - Lane Control Device, 11 - Flagger, 12 - No Passing Zone, 13 - None, 14 - Other Opposing Lanes Separated By: 1 - None, 2 - Paved Surface, 3 - Broken Painted Line, 4 - Solid Painted Line, 5 - Concrete Barrier, 6 - Metal Guard Rail, 7 - Fence, 8 - Other Barrier Trafficway Lanes: 1 - One Lane, 2 - Two Lanes, 3 - Three Lanes, 4 - Four Lanes, 5 - Five Lanes, 6 - Six Lanes or More One-Way Street: Yes/No									
Light: 1 - Daylight, 2 - Dawn, 3 - Dusk, 4 - Darkness—Road Not Lit, 5 - Darkness—Road Lit Weather: 1 - Clear, 2 - Cloudy, 3 - Rain, 4 - Snow, 5 - Sleet/Hail, 6 - Crosswind, 7 - Fog, 8 - Other Locale: 1 - Open Country, 2 - Residential, 3 - Shop's or Business, 4 - Mfg. or Industrial, 5 - School, 6 - Playground, 7 - Other Non-Vehicular Property Damage: 1 - None Visible, 2 - Uplift, 3 - Moderate, 4 - Severe Description: TRAFFIC CONTROL ROAD SIGN Owner: EAST ALABAMA PAVING COMPANY Address: OPELIKA ALABAMA									
Time Police Notified: 3:31 PM Time Police Arrived: 4:04 PM Time EMS Arrived: 4:07 PM Name of Photographer: SGT. JAMES PATTERSON Name of Investigating Officer: TROOPER ALEX F. HUNTLEY Name of Other Investigating Officers at Scene: SGT. JAMES PATTERSON Officer ID: 1109 Agency ORI: ALAST4300 Supervisor Reviewed: ALAST0300 Signature of Investigating Officer: Alex F. Huntley Date: 09-07-04									

ALABAMA

UNIFORM TRAFFIC ACCIDENT REPORT

LOCAL CASE

COPY

SHEET 2 OF 4 SHEET

7 No. 34 Rev. 4/05

SUPPLEMENTAL SHEET

Unit No.	Seat Pos.	Injury Type	Age	Sex	Election
2	3	C	35	M	N

3	Name: WILLIAM TIDWELL	Address: 1204 PETTY ROAD WESTVILLE FL	Taken to: TALLASSEE COMMUNITY HOSPITAL TALLASSEE AL	Taken by: CARE AMBULANCE
4	Name: N/A	Address:	Taken to:	Taken by:
5	Name:	Address:	Taken to:	Taken by:
6	Name:	Address:	Taken to:	Taken by:
7	Name:	Address:	Taken to:	Taken by:
8	Name:	Address:	Taken to:	Taken by:
9	Name:	Address:	Taken to:	Taken by:
10	Name:	Address:	Taken to:	Taken by:
11	Name:	Address:	Taken to:	Taken by:
12	Name:	Address:	Taken to:	Taken by:

ADDITIONAL ACCIDENT VICTIMS

ADDITIONAL NARRATIVE SPACE

DESCRIBE WHAT HAPPENED (Refer to vehicles by number) UNIT 1 WAS TRAVELING NORTHBOUND ON I-85. UNIT 1 LEFT THE LEFT SIDE OF THE ROADWAY, WENT DOWN AN EMBANKMENT, STRUCK A ROAD SIGN, STRUCK A DRAINAGE DITCH, WENT UP AN EMBANKMENT, CAME DOWN AN EMBANKMENT, STRUCK A DRAINAGE DITCH, WENT UP AN EMBANKMENT, OVERTURNED ON THE DRIVER'S SIDE, CAME BACK ONTO THE ROADWAY BLOCKING BOTH LANES OF NORTHBOUND I-85, AND IS STRUCK BY UNIT 2 TRAVELING NORTHBOUND ON I-85. AT THE TIME OF THE COLLISION DRIVER OF UNIT 2 ADVISED HE WAS UNABLE TO SEE UNIT 1 IN THE ROADWAY. INVESTIGATION REVEALED THAT AT THE TIME OF THE COLLISION DUE TO THE POSITIONING OF UNIT 1 UPON COMING BACK ONTO THE ROADWAY THE BOTTOM OF THE UNDERCARRIAGE WAS THE ONLY PART OF THE VEHICLE THAT COULD HAVE BEEN SEEN BY DRIVER OF UNIT 2. UNIT 1 WAS FURTHER TRANSPORTING TITANIUM DIOXIDE IN DRY BULK FORM. THERE WERE 22 PALLETS OF TITANIUM DIOXIDE R101-04 WITH A WEIGHT OF 2000 POUNDS EACH. THE FREIGHT WAS BEING DELIVERED TO THE STANDRIDGE COLOR CORPORATION IN SOCIAL CIRCLE GEORGIA. NONE OF THE MATERIAL WAS SPILLED NOR WERE ANY OF THE PACKAGES RUPTURED OR DAMAGED. THE MATERIAL REQUIRED PROPER HANDLING AND STORAGE DUE TO ITS POTENTIAL TO BECOME HAZARDOUS. ALL HANDLING AND STORAGE WAS DONE BY THROWER'S WRECKER SERVICE.